```
R 301650Z MAY 00
 FM USS BARRY
 TO AIC NORFOLK VA//D13//
 COMFIFTHFLT//N2/N3/N34//
 INFO CINCUSNAVEUR LONDON UK//N2/N3/N5//
 CINCUSNAVEUR LONDON UK//N2/N3/N5//
 USTRANSCOM SCOTT AFB IL//TCJ2-J//
 JAC MOLESWORTH RAF MOLESWORTH UK//DOA//
 CTF 50
 COMIKEBATGRU
 COMDESKON TWO SIX
 TF 50
 BT
 UNCLAS//N03510//
 OPER///
MSGID/GENADMIN/BARRY//
 SUBJ/NIIP PROGRAM FORMATTED LESSONS LEARNED SUBMISSION
ADEN, YEMEN//
RMKS/DATA FORMATTED FOR PROCESSING BY NIIP SOFTWARE.//
CAPSCHECK/F//
 IIPID/54835-30841/U/-/-/-/-//
CLASDAT/-/-//
TITLE/PORT VISIT REPORT TO ADEN, YEMEN//
OPEXCMD/-/DDG52//
                    626-7001/-//
LLPOC/LTJG
OBSTXT/U/-/-/1. PORT VISIT SUMMARY. //
///
    A. NAME OF PORT: ADEN, YEMEN//
1.
///
    B. GEOGRAPHIC LOCATION: SOUTH WEST COAST OF YEMEN //
///
    C. NAME OF VESSEL: USS BARRY (DDG 52) //
111
1
    D. NAME OF COMMANDING OFFICER:
111.
    E. DATE OF VISIT: 23 MAY 00 //
    F. TIME ZONE: -3C//
111
    NAVIGATIONAL INFORMATION.//
/2.
///
    A. DESCRIPTION OF PORT: ADEN IS A SMALL INDUSTRIAL PORT WITH
/MODERN FUELING FACILITIES. SOME YEMENI NAVAL VESSELS ARE
/STATIONED IN ADEN.//
111
    B. APPROACHES, LIGHTS, ETC.: BARRY USED NIMA CHARTS 62097
/AND 62098 AS APPROACH AND HARBOR CHARTS RESPECTIVELY.
/CHARTS WERE ACCURATE AND ADEQUATE FOR NAVIGATION INTO ADEN.
/PROMINENT NAVAIDS USED FOR BOTH APPROACH AND DEPARTURE WERE THE
/SIGNAL STATION AND CLOCK TOWER ON CHART 92098.
111
    C. PILOTAGE: PILOTAGE IS COMPULSORY.
                                           PILOT WAS PICKED UP AT
/PILOT PICKUP POINT 3 NM SOUTH OF THE ENTRANCE CHANNEL.
    D. ENTRANCE: LOCATED BETWEEN ADEN AS SUGHRA AND THE ADEN
/PENINSULA, THE ENTRANCE IS VERY WELL DEFINED AND FREE OF
/HAZARDS.//
111
   E. CHANNEL: WELL MARKED BY CHARTED BUOYS AND EASY TO FOLLOW.
1 11
111
   F. ANCHORAGES:NC //
111
```

HROLICAL

Encl (54)

Page 1 of 3

```
G. WRECKS AND OBSTRUCTIONS: NC //
///
/
    H. TIDES AND CURRENTS: NC//
///
    I. WEATHER AND WINDS: BARRY EXPERIENCED SLIGHT HAZE DURING
/THE MORNING APPROACH TO ADEN. VISIBILITY WAS APPROXIMATELY 6
/NM. UPON DEPARTURE, AT 1600 (L) VISIBILITY WAS UNRESTRICTED.//
DISTXT/U/-/-/3. BERTHING AND FACILITIES.//
    A. MOORINGS, DOCKS, ETC.: BARRY MOORED TO REFUELING BUNKER
/SEVEN IN POSITION //
/12 47.951N/044 58.942E WITH 13 FT BENEATH THE KEEL.//
    B. FUEL, LUBE AND DIESEL OIL: BARRY RECEIVED 86K OF F-76.
/BARRY STATION 8 WAS ALIGNED WITH REFUELING RIG AND TRANSFER
/TOOK APPROXIMATELY 3 HOURS.
                                //
    C. MECHANICAL HANDLING FACILITIES: NA //
111
    D. DRY-DOCKS AND REPAIR FACILITIES: NA//
    E. WAREHOUSE AND STORAGE FACILITIES: NA// .
111
    F. STEVEDORES: NA//
111
    G. PORT CAPACITY: NA//
/
111
    H. ROAD, RAIL AND STEAMER TRANSPORTATION: NA//
LLTXT/U/-/-/4. SERVICES, LOGISTICS AND OPERATIONS.//
   A. LIGHTERAGE: TWO TUGS WERE AVAILABLE AND USED TO MOOR.
/PILOT WAS COMPETENT AND CORDIAL. EXPECT PILOT TO BRING UNITED
/YEMEN FLAG TO BE FLOWN.//
111
   B. DREDGES AND MISCELLANEOUS CRAFT: NA//
111
   C. WATER: BARRY DID NOT TAKE ON WATER. //
111
   D. AIRFIELDS: NA//
111
   E. COMMUNICATIONS: PILOTS AND ADEN HARBOR CONTROL CAN BE
/REACHED ON BTB 13 AND 16.//
   F. MEDICAL: NA//
/
111
1
   G. GASOLINE: NA//
111
   H. PROVISIONS: NA//
/
111
   I. GARBAGE DISPOSAL: GARBAGE DISPOSAL WAS PROVIDED BY
/HUSBANDING AGENT VIA SMALL BOAT. BOAT MADE ONE TRIP AT A COST
/OF $150.//
RECTXT/U/-/-/5. PERSONALIA.//
111
                                                          BRITISH
    A. CALLS: LTCOL
                                  AND MR..
/CONSUL GENERAL WERE HOSTED FOR LUNCH.//
///
    B. HONORS: NA//
111
/6. PORT VISIT INFORMATION.//
111
    A. GENERAL INFORMATION: BARRY ONLY IN ADEN FOR 6 HOURS TO
/SHORE BUNKER.//
111
```

UNCLASSIFIED

```
B. LIBERTY: NA//
      C. CLUBS AND BARS: NA//
      D. RESTAURANTS: NA//
 111
     E. HOTELS: NA//
     F. ATHLETICS: NA//
111
     G. BEACHES: NA//
111
     H. CHURCHES: NA//
111
     I. TRANSPORTATION: NA//
111
     J. TOURS: NA//
111
     K. SHOPPING: NA//
111
     L. THEATER AND MOVIES: NA//
111
     M. PHYSICAL SECURITY: NA//
111
     N. MISCELLANEOUS INFORMATION: THE DEPLOYMENT FLAG PACKAGE
/FROM RSG NORFOLK CONTAINED THE OLD NORTH YEMEN FLAG VICE THE NEW
/UNITED YEMEN FLAG. PILOT WILL PROVIDE NEW FLAG TO SHIPS WHEN HE
/BOARDS.
         11
/PORT COSTS WERE VERY REASONABLE, HOWEVER, THERE WERE TWO SMALL
/MISC CHARGES; $100 LIGHT DUES AND $25 LEAVING FEE.//
```

Encl (54) Page 3 of 3